## ORDINANCE

AN ORDINANCE ORDERING THE DEMOLITION AND REMOVAL OF THE DWELLING AT 1040 ROSADA AVENUE PURSUANT TO THE HOUSING CODE OF THE CITY OF CHARLOTTE AND ARTICLE 19, PART 6, CHAPTER 160A OF THE GENERAL STATUTES OF NORTH CAROLINA, SAID BUILDING BEING THE PROPERTY OF UNKNOWN HEIRS OF VIVIAN E. WALBAUM 1040 ROSADA AVENUE CHARLOTTE, NC 28213

WHEREAS, the dwelling located at 1040 Rosada Avenue in the City of Charlotte has been found by the Code Enforcement Official of the City of Charlotte to be in violation of the Housing Code of the City of Charlotte and the owners thereof have been ordered to demolish and remove said dwelling; and

WHEREAS, said owner(s) have failed to comply in a timely fashion.

NOW, THEREFORE, BE IT ORDAINED by the City Council of the City of Charlotte, North Carolina, that the Code Enforcement Official of the City of Charlotte is hereby ordered to cause the demolition and removal of the dwelling located at 1040 Rosada Avenue in the City of Charlotte in accordance with the Housing Code of the City of Charlotte. This Ordinance shall become effective upon its adoption.

APPROVED AS TO FORM:

Senior Assistant City Attorney

0 Rosada Avenue ghborhood Profile Area known Heirs of vian E. Walbaum 0 Rosada Avenue
known Heirs of vian E. Walbaum
known Heirs of vian E. Walbaum
vian E. Walbaum
vian E. Walbaum
0 Rosada Avenue
arlotte, NC 28213
using & Neighborhood velopment & Community ety Plan
lic Agency Referral from arlotte Fire Dept.
03/2020
07/2020
22/2020
13/2021
15/2021
03/2021

### NOTIFICATION TO OWNER

Owner and parties of interest have been advised that failure to comply with the Order to Demolish the structure would result in City Council being requested to approve demolition by the City and a lien being placed on the property for the cost of demolition.

#### **OPTIONS**


IN-REM REPAIR	REHAB TO CITY STANDARD	REPLACEMENT HOUSING	DEMOLITION
Estimated In-Rem Repair	Acquisition & Rehabilitation Cost	New Replacement Structure Cost	Estimated
Cost: \$81,760	(Existing structure: 1,424 sq. ft. total)	(Structure: 1,424 sq. ft. total)	Demolition
	Economic Life: 15-20 years	Economic Life: 50 years	Cost
	Estimated cost-\$189,333	Estimated cost-\$225,389	\$9,000
In-Rem Repair is not	Acquisition:	Acquisition:	
recommended because	Tax values:	Tax values	
the In-Rem Repair cost is	- Structure: \$ 90,200	- Structure: \$ 90,200	
greater than 65% of the	- Land: <u>\$ 20,000</u>	- Land: <u>\$ 20,000</u>	
tax value.	Total Acquisition:\$ 110,200	Total Acquisition: \$ 110,200	
	Estimated Rehabilitation	New structure: \$ 98,256	
	Cost: \$ 71,200	Estimated demolition cost: \$ 9,000	
	Outstanding Loans \$ 0	Outstanding Loans: \$ 0	
	Property Taxes owed: \$ 6,227	Property Taxes owed: \$ 6,227	
	Interest on Taxes owed: \$ 1,706	Interest on Taxes owed: <u>\$ 1,706</u>	
	Total: \$ 79,133	Total: \$ 115,189	

#### Demolition is recommended because:

Estimated In-Rem Repair cost of \$81,760 (\$57.41/sq. ft.), which is 90.643% of the structure tax value, which is \$90,200.

- City rehab costs analysis shows that rehabilitation is not feasible because the cost is prohibitive.
- New construction analysis shows that new construction is not feasible because the cost is prohibitive.
- Violations include: Structural, electrical, plumbing and heating violations. Fire damaged flooring and wall framing. Damaged wall, ceiling and floor covering. Fire damaged windows. Missing entry door. Damaged electrical and plumbing fixtures. Heating equipment not operational. Fire damaged roof covering, sheathing and rafters.
- The building is 54 years old and consists of 1,424 square feet total.
- A new 1,424 sq. ft. structure can be built for \$98,256.

# 1040 Rosada Avenue



# 1040 Rosada Avenue

