### **ORDINANCE**

AN ORDINANCE ORDERING THE DEMOLITION AND REMOVAL OF THE DWELLING AT 4730 THORNWOOD ROAD PURSUANT TO THE HOUSING CODE OF THE CITY OF CHARLOTTE AND ARTICLE 19, PART 6, CHAPTER 160A OF THE GENERAL STATUTES OF NORTH CAROLINA, SAID BUILDING BEING THE PROPERTY OF HENRIETTA E. LYNAH ANDYINDRA LYNAH 4110-112 DOUBLE CREEK CROSSING DRIVE CHARLOTTE, NC 28269

WHEREAS, the dwelling located at 4730 Thornwood Road in the City of Charlotte has been found by the Code Enforcement Official of the City of Charlotte to be in violation of the Housing Code of the City of Charlotte and the owners thereof have been ordered to demolish and remove said dwelling; and

WHEREAS, said owner(s) have failed to comply in a timely fashion.

NOW, THEREFORE, BE IT ORDAINED by the City Council of the City of Charlotte, North Carolina, that the Code Enforcement Official of the City of Charlotte is hereby ordered to cause the demolition and removal of the dwelling located at 4730 Thornwood Road in the City of Charlotte in accordance with the Housing Code of the City of Charlotte. This Ordinance shall become effective upon its adoption.

APPROVED AS TO FORM:	
Senior Assistant City Attorne	

GENERAL INFORMATION			
Property Address	4730 Thornwood Road		
Neighborhood	Neighborhood Profile Area		
	371		
Council District	#4		
Owner(s)	Henrietta E. Lynah		
- · · · · · · · · · · · · · · · · · · ·	Yindra Lynah		
Owner(s) Address	4110-112 Double Creek Crossing		
	Drive Charlette NC 28260		
	Charlotte, NC 28269		
KEY FACTS			
	Housing & Neighborhood		
Focus Area	Development & Community Safety Plan		
	Surety I lun		
CODE ENFORCEMENT INFORMATION			
♦ Reason for Inspection:	Charlotte Fire Department		
♦ Date of the Inspection:	07/12/2017		
◆ Received title search; revealing party in interest:	10/17/2017		
◆ Owner(s) and party in interest notified of Complaint	05/11/2018		
and Notice of Hearing by advertisement and certified mail by:	07/26/2019		
◆ Held hearing for owner(s) and party in interest by:	05/25/2018		
v Tiera hearing for owner(s) and party in interest by:	08/21/2019		
◆ Owner(s) and party in interest attend hearing:	No		
◆ Owner(s) and party in interest ordered to demolish	06/25/2018		
structure by:	09/27/2019		
◆ Filed Lis Pendens:	10/09/2018 01/08/2020		
◆ Updated title search; no change:	07/08/2019		
◆ Owner(s) have not repaired or complied with order to	07/00/2019		
demolish.			
◆ Structure occupied:	No		
◆ Estimated demolition cost:	\$11,360		
◆ Lien will be placed on the property for the cost of			
Demolition.			

#### NOTIFICATION TO OWNER

Owner and parties of interest have been advised that failure to comply with the Order to Demolish the structure would result in City Council being requested to approve demolition by the City and a lien being placed on the property for the cost of demolition.

#### **OPTIONS**

IN-REM REPAIR	REHAB TO CITY STANDARD		REPLACEMENT	HOUSING	DEMOLITION
Estimated In-Rem Repair	Acquisition & Rehabilitation Cost		New Replacement Structure Cost		Estimated
Cost: \$46,475	(Existing structure: 2,187 sq. ft. total)		(Structure: 2,187	sq. ft. total)	Demolition
	Economic Life: 15-20 years		Economic Life: 50 years		Cost
	Estimated cost-\$154,933		Estimated cost-\$207,846		\$11,360
In-Rem Repair is not	Acquisition:		Acquisition:		
recommended because	Tax values:		Tax values		
the In-Rem Repair cost is	- Structure:	\$ 1,900	- Structure:	\$ 1,900	
greater than 65% of the	- Terrance:	\$ 100	- Terrace:	\$ 100	
tax value.	- Land:	\$ 20,000	- Land:	\$ 20,000	
	Total Acquisition:	\$ 22,000	Total Acquisition:	\$ 22,000	
	Estimated Rehabilitation		New structure:	\$ 150,903	
	Cost:	\$ 109,350	Estimated demolition cost:	\$ 11,360	
	Outstanding Loans	\$ 22,000	Outstanding Loans:	\$ 22,000	
	Property Taxes owed:	\$ 1,422	Property Taxes owed:	\$ 1,422	
	Interest on Taxes owed:	<u>\$ 161</u>	Interest on Taxes owed:	<u>\$ 161</u>	
	Total:	\$ 132,933	Total:	\$ 185,846	


#### RECOMMENDATION FOR DEMOLITION

Demolition is recommended because:

Estimated In-Rem Repair cost of: \$46,475 (\$21.25 /sq. ft.), which is 2,446% of the structure tax value, which is \$1,900.

- City rehab costs analysis shows that rehabilitation is not feasible because the cost is prohibitive.
- New construction analysis shows that new construction is not feasible because the cost is prohibitive.
- Violations include: Structural, electrical and heating violations. Moisture damaged ceiling and wall covering throughout. Broken window glass. Exterior siding and trim decayed/loose and missing in areas. Ductwork for heating equipment damaged. Electrical wiring damaged. Roof covering and sheathing damaged. Fire damaged roof rafters.
- The building is 58 years old and consists of 2,187 square feet total.
- A new 2,187 sq. ft. structure can be built for \$150,903.

# 4730 Thornwood Road



## 4730 Thornwood Road







