

ORDINANCE

AN ORDINANCE ORDERING THE DEMOLITION AND REMOVAL OF THE ACCESSORY STRUCTURE AT 925 HOMEWOOD PLACE PURSUANT TO THE HOUSING CODE OF THE CITY OF CHARLOTTE AND ARTICLE 19, PART 6, CHAPTER 160A OF THE GENERAL STATUTES OF NORTH CAROLINA, SAID STRUCTURE BEING THE PROPERTY OF MICHAEL EUGENE CROWE, MILTON LEWIS CROWE, WAYNE MAURICE CROWE 925 HOMEWOOD PLACE CHARLOTTE, NC 28217

WHEREAS, the accessory structure located at 925 Homewood Place in the City of Charlotte has been found by the Code Enforcement Official of the City of Charlotte to be in violation of the Housing Code of the City of Charlotte and the owners thereof have been ordered to demolish and remove said structure(s); and

WHEREAS, said owner(s) have failed to comply in a timely fashion.

NOW, THEREFORE, BE IT ORDAINED by the City Council of the City of Charlotte, North Carolina, that the Code Enforcement Official of the City of Charlotte is hereby ordered to cause the demolition and removal of the accessory structure located at 925 Homewood Place the City of Charlotte in accordance with the Housing Code of the City of Charlotte. This Ordinance shall become effective upon its adoption.

APPROVED AS TO FORM:

Senior Assistant City Attorney

GENERAL INFORMATION	
Property Address	925 Homewood Place (Accessory Structure)
Neighborhood	Neighborhood Profile Area 362
Council District	#3
Owner(s)	Michael Eugene Crowe Milton Lewis Crowe Wayne Maurice Crowe
Owner(s) Address	925 Homewood Place Charlotte, NC 28217
KEY FACTS	
Focus Area	Housing & Neighborhood Development & Community Safety Plan
CODE ENFORCEMENT INFORMATION	
◆ Reason for Inspection:	Field Observation
◆ Date of the Inspection:	02/12/2018
◆ Received title search revealing party in interest:	08/31/2018
◆ Owner(s) and party in interest notified of Complaint and Notice of Hearing by advertisement and certified mail by:	12/03/2018
◆ Held hearing for owner(s) and party in interest by:	01/03/2019
◆ Owner(s) and party in interest attend hearing:	Yes
◆ Received intent to repair letter from owner(s):	01/17/2019
◆ Owner(s) and party in interest ordered to demolish structure by:	02/08/2019
◆ Updated title search; no change:	06/12/2019
◆ Issued Supplemental Order to both owner(s) and party in interest to repair structure by:	07/01/2019
◆ Filed Lis Pendens:	07/10/2019
◆ Owner(s) have not repaired or complied with order to demolish.	
◆ Structure(s) occupied:	No
◆ Estimated demolition cost:	\$4,000
◆ Lien will be placed on the property for the cost of Demolition.	

NOTIFICATION TO OWNER

Owner and parties of interest have been advised that failure to comply with the Order to Demolish the structure would result in City Council being requested to approve demolition by the City and a lien being placed on the property for the cost of demolition.

OPTIONS


IN-REM REPAIR	REHAB TO CITY STANDARD	REPLACEMENT HOUSING	DEMOLITION
In-Rem Repair is not recommended. Because this is an accessory structure.	Acquisition & Rehabilitation Cost	New Replacement Structure Cost	Estimated demolition Cost \$4,000
	Acquisition and rehabilitation are not applicable.	Replacement housing is not applicable.	

RECOMMENDATION FOR DEMOLITION

Demolition is recommended because:

- City rehab costs analysis is not applicable.
- New construction analysis is not applicable.
- Violation: Accessory structure not in safe and substantial condition.

925 Homewood Place



925 Homewood Pl

14515504

Manchester Dr

Homewood Pl

Blandwood Dr



100 Feet

925 Homewood Place (Accessory Building)

