## **ORDINANCE**

AN ORDINANCE ORDERING THE DEMOLITION AND REMOVAL OF THE DWELLING AT 4336 CONNELLY CIRCLE PURSUANT TO THE HOUSING CODE OF THE CITY OF CHARLOTTE AND ARTICLE 19, PART 6, CHAPTER 160A OF THE GENERAL STATUTES OF NORTH CAROLINA, SAID BUILDING BEING THE PROPERTY OF UNKNOWN HEIRS OF WILLETTE W. WOODS 4336 CONNELLY CIRCLE CHARLOTTE, NC 28208

WHEREAS, the dwelling located at 4336 Connelly Circle in the City of Charlotte has been found by the Code Enforcement Official of the City of Charlotte to be in violation of the Housing Code of the City of Charlotte and the owners thereof have been ordered to demolish and remove said dwelling; and

WHEREAS, said owner(s) have failed to comply in a timely fashion.

NOW, THEREFORE, BE IT ORDAINED by the City Council of the City of Charlotte, North Carolina, that the Code Enforcement Official of the City of Charlotte is hereby ordered to cause the demolition and removal of the dwelling located at 4336 Connelly Circle in the City of Charlotte in accordance with the Housing Code of the City of Charlotte. This Ordinance shall become effective upon its adoption.

APPROVED AS TO FORM:

Senior Assistant City Attorney

GENERAL INFORMATION			
Property Address	4336 Connelly Circle		
Neighborhood	Neighborhood Profile Area		
Council District	#3		
Owner(s)	Unknown Heirs of Willette W. Woods		
Owner(s) Address	4336 Connelly Circle Charlotte, NC 28208		
KEY FACTS			
Focus Area	Housing & Neighborhood Development & Community Safety Plan		
CODE ENFORCEMENT INFORMATION			
♦ Reason for Inspection:	Public Agency Referral Charlotte Fire Department		
◆ Date of the Inspection:	01/10/2017		
♦ Received title search:	02/23/2017		
◆ Owner(s) notified of Complaint and Notice of Hearing by advertisement and certified mail by:	03/10/2017		
♦ Held hearing for owner(s) by:	04/04/2017		
◆ Owner(s) attend hearing:	No		
◆ Owner(s) ordered to demolish structure by:	09/18/2017		
♦ Filed Lis Pendens:	03/23/2017 10/11/2017		
♦ Owner(s) have not repaired, or complied with order to demolish.			
♦ Structure occupied:	No		
♦ Estimated demolition cost:	\$5,070		
◆ Lien will be placed on the property for the cost of Demolition.			

### NOTIFICATION TO OWNER

Owner and parties of interest have been advised that failure to comply with the Order to Demolish the structure would result in City Council being requested to approve demolition by the City and a lien being placed on the property for the cost of demolition.

#### **OPTIONS**

IN-REM REPAIR	REHAB TO CITY STANDARD		REPLACEMENT HOUSING		DEMOLITION
Estimated In-Rem Repair	Acquisition & Rehabilitation Cost		New Replacement Structure Cost		Estimated
Cost: \$70,295	(Existing structure: 1,057 sq. ft. total)		(Structure: 1,057 sq. ft. total)		Demolition
	Economic Life: 15-20 years		Economic Life: 50 years		Cost
	Estimated cost-\$132,223		Estimated cost-\$157,376		\$5,070
In-Rem Repair is not	Acquisition:		Acquisition:		
recommended because	Tax values:		Tax values		
the In-Rem Repair cost is	- Structure: \$	37,500	- Structure:	\$ 37,500	
greater than 65% of the	- Land: <u>\$</u>	33,200	- Land:	\$ 33,200	
tax value.	Total Acquisition: \$	70,700	Total Acquisition:	\$ 70,700	
	Estimated Rehabilitation		New structure:	\$ 72,933	
	Cost: \$	52,850	Estimated demolition cost:	\$ 5,070	
	Outstanding Loans \$	0	Outstanding Loans:	\$ 0	
	Property Taxes owed: \$	6,682	Property Taxes owed:	\$ 6,682	
	Interest on Taxes owed: \$	1,991	Interest on Taxes owed:	\$ 1,99 <u>1</u>	
	Total: \$	61,523	Total:	\$ 86,676	


### RECOMMENDATION FOR DEMOLITION

#### Demolition is recommended because:

Estimated In-Rem Repair cost of: \$70,295 (\$66.50 /sq. ft.), which is 187.45% of the structure tax value, which is \$37,500.

- City rehab costs analysis shows that rehabilitation is not feasible because the cost is prohibitive.
- New construction analysis shows that new construction is not feasible because the cost is prohibitive.
- Violations include: Structural, electrical, plumbing and heating violations. Fire damaged interior ceiling and wall covering. Windows are damaged. Fire damaged wall structure, roof rafters and sheathing. Fire damaged electrical wiring. Plumbing supply and drain piping damaged. Fire damaged heating equipment and water heater. Accessory building not in safe substantial condition.
- The building is 71 years old and consists of 1,057 square feet total.
- A new 1,057 sq. ft. structure can be built for \$72,933.

# **4336 Connelly Circle**



4336 Connelly Circle







