ORDINANCE

AN ORDINANCE ORDERING THE DEMOLITION AND REMOVAL OF THE DWELLING AT 2526 ELMIN STREET PURSUANT TO THE HOUSING CODE OF THE CITY OF CHARLOTTE AND ARTICLE 19, PART 6, CHAPTER 160A OF THE GENERAL STATUTES OF NORTH CAROLINA, SAID BUILDING BEING THE PROPERTY OF ASA HOME MANAGEMENT LLC 1900 SUNSET HARBOUR DRIVE $2^{\rm ND}$ FLOOR MIAMI, FL 33139

WHEREAS, the dwelling located at 2526 Elmin Street in the City of Charlotte has been found by the Code Enforcement Official of the City of Charlotte to be in violation of the Housing Code of the City of Charlotte and the owners thereof have been ordered to demolish and remove said dwelling; and

WHEREAS, said owner(s) have failed to comply in a timely fashion.

NOW, THEREFORE, BE IT ORDAINED by the City Council of the City of Charlotte, North Carolina, that the Code Enforcement Official of the City of Charlotte is hereby ordered to cause the demolition and removal of the dwelling located at 2526 Elmin Street in the City of Charlotte in accordance with the Housing Code of the City of Charlotte. This Ordinance shall become effective upon its adoption.

APPROVED AS TO FORM:	
Senior Assistant City Attorney	7

Property Address	2526 Elmin Street				
	Neighborhood Profile Area				
Neighborhood	120				
Council District	#3				
Council District					
Owner(s)	ASA Home Management LLC				
Owner(s) Address	1900 Sunset Harbour Drive 2 nd Floor				
	Miami, FL 33139				
KEY FACTS					
Focus Area	Housing & Neighborhood Development & Community Safety Plan				
CODE ENFORCEMENT INFORMATION					
♦ Reason for Inspection:	Field Observation				
♦ Date of the Inspection:	08/02/2017				
♦ Received title search:	08/22/2017				
◆ Owner(s) notified of Complaint and Notice of Hearing by advertisement and certified mail by:	10/17/2017 10/18/2017				
♦ Held hearing for Owner(s) by:	11/10/2017				
♦ Owner(s) attend hearing:	No				
♦ Owner(s) ordered to demolish structure by:	12/18/2017				
♦ Filed Lis Pendens:	01/19/2018 02/01/2018				
♦ Owner(s) have not repaired, or complied with order to demolish.					
◆ Structure occupied:	No				
♦ Estimated demolition cost:	\$6,840				

NOTIFICATION TO OWNER

Owner and parties of interest have been advised that failure to comply with the Order to Demolish the structure would result in City Council being requested to approve demolition by the City and a lien being placed on the property for the cost of demolition.

OPTIONS

IN-REM REPAIR	REHAB TO CITY STANDARD		REPLACEMENT HOUSING				DEMOLITION	
Estimated In-Rem Repair	Acquisition & Rehabilitation Cost		New Replacement	t Structure Cost			Estimated	
Cost: \$43,665	(Existing structure: 1,303 sq. ft. total)		(Structure: 1,303 sq. ft. total)				Demolition	
	Economic Life: 15-20 years		Economic Life: 50 years				Cost	
	Estimated cost-\$137,294		Estimated cost-	Estimated cost-\$168,891			\$6,840	
In-Rem Repair is not	Acquisition:			Acquisition:				
recommended because	Tax values:			Tax values				
the In-Rem Repair cost is	- Structure:	\$	57,400	- Structure:	\$	57,400		
greater than 65% of the	- Patio:	\$	300	- Patio :	\$	300		
tax value.	- Land:	\$	13,400	- Land:	\$	13,400		
	Total Acquisition:	\$	71,100	Total Acquisition:	\$	71,100		
	Estimated Rehabilitation			New structure:	\$	89,907		
	Cost:	\$	65,150	Estimated demolition cost:	\$	6,840		
	Outstanding Loans	\$	0	Outstanding Loans:	\$	0		
	Property Taxes owed:	\$	1,017	Property Taxes owed:	\$	1,017		
	Interest on Taxes owed:	\$	27	Interest on Taxes owed:	\$	27		
	Total:	\$	66,194	Total:	\$	97,791		


RECOMMENDATION FOR DEMOLITION

Demolition is recommended because:

Estimated In-Rem Repair cost of: \$43,665 (\$33.51/sq. ft.), which is 76.07% of the structure tax value, which is \$57,400.

- City rehab costs analysis shows that rehabilitation is not feasible because the cost is prohibitive.
- New construction analysis shows that new construction is not feasible because the cost is prohibitive.
- Violations include: Structural, electrical, plumbing and heating violations. Walls and ceiling covering missing/damaged in areas.
 Missing/damaged entry doors. Missing floor covering. Broken window panes. Damaged roof covering. Electrical wiring, fixtures and receptacles damaged or missing. Missing plumbing fixtures. No heat source provided.
- The building is 15 years old and consists of 1,301 square feet total.
- A new 1,301 sq. ft. structure can be built for \$89,907.

2526 Elmin Street



2526 Elmin Street







