ORDINANCE

AN ORDINANCE ORDERING THE DEMOLITION AND REMOVAL OF THE ACCESSORY STRUCTURE AT 2817 DALECREST DRIVE PURSUANT TO THE HOUSING CODE OF THE CITY OF CHARLOTTE AND ARTICLE 19, PART 6, CHAPTER 160A OF THE GENERAL STATUTES OF NORTH CAROLINA, SAID STRUCTURE BEING THE PROPERTY OF JOHN C. MCCOY AND JERVENE S. MCCOY 2817 DALECREST DRIVE CHARLOTTE, NC 28269

WHEREAS, the accessory structure located at 2817 Dalecrest Drive in the City of Charlotte has been found by the Code Enforcement Official of the City of Charlotte to be in violation of the Housing Code of the City of Charlotte and the owners thereof have been ordered to demolish and remove said structure(s); and

WHEREAS, said owner(s) have failed to comply in a timely fashion.

NOW, THEREFORE, BE IT ORDAINED by the City Council of the City of Charlotte, North Carolina, that the Code Enforcement Official of the City of Charlotte is hereby ordered to cause the demolition and removal of the accessory structure located at 2817 Dalecrest Drive the City of Charlotte in accordance with the Housing Code of the City of Charlotte. This Ordinance shall become effective upon its adoption.

Senior Assistant City Attorne	

GENERAL INFORMATION		
	2817 Dalecrest Drive	
Property Address	(Accessory Structure)	
Neighborhood	Neighborhood Profile Area	
reignoomood	160	
Council District	#4	
Owner(s)	John C. McCoy and	
Owner(s)	Jervene S. McCoy	
Owner(s) Address	2817 Dalecrest Drive	
o mor(s) riadioss	Charlotte, NC 28269	
KEY FACTS		
	Housing & Neighborhood	
Focus Area	Development & Community	
	Safety Plan	
CODE ENFORCEMENT INFORMATION		
♦ Reason for Inspection:	Petition	
◆ Date of the Inspection:	08/20/2018	
◆ Owner(s) notified of Complaint and Notice of Hearing by advertisement and certified mail by:	08/23/2018	
♦ Received title search:	09/06/2018	
♦ Held hearing for owner(s) by:	09/19/2018	
♦ Owner(s) attend hearing:	Yes	
♦ Owner(s) ordered to demolish structure by:	10/22/2018	
♦ Filed Lis Pendens:	01/08/2019	
♦ Extensions granted to Owner(s)	12/28/2018	
	03/09/2019	
♦ Owner(s) have not repaired, or complied with order to demolish.		
♦ Structure(s) occupied:	No	
♦ Estimated demolition cost:	\$2,500	
◆ Lien will be placed on the property for the cost of Demolition.		

NOTIFICATION TO OWNER

Owner and parties of interest have been advised that failure to comply with the Order to Demolish the structure would result in City Council being requested to approve demolition by the City and a lien being placed on the property for the cost of demolition.

OPTIONS


IN-REM REPAIR	REHAB TO CITY STANDARD	REPLACEMENT HOUSING	DEMOLITION
IN-KEWI KEFAIK	KEHAD TO CITT STANDARD	KEPLACEMENT HOUSING	DEMOLITION
In-Rem Repair is not recommended. Because this is an accessory	Acquisition & Rehabilitation Cost	New Replacement Structure Cost	Estimated demolition Cost
uns is an accessory			Cost
structure.			\$2,500
	Acquisition and rehabilitation are not applicable.	Replacement housing is not applicable.	

RECOMMENDATION FOR DEMOLITION

Demolition is recommended because:

- City rehab costs analysis is not applicable.
- New construction analysis is not applicable.
- Violation: Accessory structure not in safe and substantial condition.

2817 Dalecrest Drive



2817 Dalecrest Drive (Accessory Building)







